




CASE STUDY: Max & Erma's

LOCATION: MONROEVILLE, PA



SITUATION:

The main entrance to the restaurant had significantly deteriorated concrete on both the sidewalk and curbing. This needed to be corrected because it was creating a trip hazard for patrons. Tearing out all of the existing concrete and pouring new, however, was determined to be extremely costly and disruptive to business.

-  Solution: Simon HD Concrete Resurfacing
-  Concrete Repair
-  Curb Replacement

BEFORE



AFTER



BEFORE



AFTER



SOLUTION:

For the majority of the affected areas, Simon Surfaces was able to resurface the existing concrete base with Simon HD – a heavy duty solution for interior and exterior concrete. In addition, 65 linear feet of concrete repairs were performed and about 12 linear feet of curbing was replaced. All trip hazards are resolved and there no downtime – all work was performed after business hours.

