

CASE STUDY:

Home Improvement Store

LOCATION: SPRINGFIELD, OH

Concrete Repairs + Simon HD


SITUATION

There were several parts of the large home improvement retail store – including both indoor and outdoor storage and shopping areas – that had deteriorated concrete consisting of cracks, spalling, and more. Plus, the entrance to the store was unlevel and was cracked, which was causing shoppers' carts to get stuck as well as posing a safety hazard. The surfaces of the shopping areas had cracks and concrete damage throughout, which were causing trip hazards for both employees and customers. The floor of the storage area had been repaired multiple times and the entire area was failing.


Before



After



After



800.523.7714 • www.simonsurfaces.com

SIMON SURFACES™

CASE STUDY: Home Improvement Store

LOCATION: SPRINGFIELD, OH




Concrete Repairs + Simon HD

SOLUTION


Simon Surfaces performed both concrete repairs and concrete restoration across the various surfaces, depending on need. All cracks were filled in throughout all floors, including the interior storage areas and exterior garden center shopping areas. The concrete entrance was completely restored using Simon HD to eliminate all of the bumps and cracks causing safety concerns. The storage area floor was also restored with Simon HD due to the extent of the damage from numerous previous repairs.

Before



The Simon Surfaces team worked with the facility manager to strategically schedule the individual sections of necessary work. All work was performed during the evening hours after the store was closed. The garden center remained open the entire time and the entire project was completed within two weeks.

After



800.523.7714 • www.simonsurfaces.com